

SERVICE BULLETIN

Aircraft Type:

ALTO 912 TG

No. SB-0-001-2017-EN

MANDATORY

Revision:

00

1) Planning information

Applicability:

S/N: DF064/2016; DF067/2016; DF068/2016; DF069/2017; DF070/2017;

DF071/2017; DF072/2017; DF073/2017; DF074/2017

Concurrent ASB/SB/SI and SL:

None

Reason:

Due to typing error and data unification in POH

Subject:

Perform a manual correction in POH

Compliance:

Immediately

Approval:

None

Labour time:

0.1 hr

Mass data:

Change of weight:

none

Moment of inertia:

none

Electrical load data:

None

Software modifications:

None

References:

None

Other Publications affected:

Pilot Operating Handbook

Interchangeability of part:

None

2) Material Information

Material-cost and availability:

None

Company support information:

None

Material requirement per aircraft:

None

Material requirement per spare part:

None

Rework of parts:

None

Special tooling and availability:

None

3) Accomplishment/Instructions

Instructions:

Perform manual correction in POH, chapter 2.1 Speed limitations.
Speeds and index need to be changed regarding to following figure:

Speed		IAS [km/h]
Varo	Stall speed with extended flaps	,6064
Vsø	Stall speed with retracted flaps	80 78

2) Write performed revision to Record of revisions in POH, page 3.

Summary:

None

Inquiries:

None

DECEMBER 20, 2017

For current valid documentation see:

SB-0-001-2017-EN



SERVICE BULLETIN

Aircraft Type:

ALTO 912 TG

No. SB-0-001-2017-EN

MANDATORY

Revision:

00

4) Appendix

None

Issued by:

JAN SPONER

Signature:

Approved by:

IVO LEDERER

Signature

DIRECT

Direct Fly s.r.o. Špitálka 8 602 00 Brno Czech Republic DIČ: CZ27683737

Stamp